

Professionale DPF+EGR REMOVER 3.0 Lambda Hotstart Flap, O2, DTC 2 SOFTWARE FULL

Top 6 Motivi per comprare software per la modifica del DPF \ FAP - EGR:

1. il software è compatibile con FGTECH Galletto, KESS V2, KTAG Master, CMD ect. Lettori - scrittori file che lavorano al 100% con questi programmi.
2. I programmi DPF-EGR professionali supportati ai file binari di formato 100%.
3. Bosch, Siemens, Denso, Visteon, Delphi, Marelli, Transtron ECU sono supportati !!
4. Supportato da WinXP a Win8.1, Win10 (32 + 64 bit)
5. Multi-lingue Supporta : English, German, French, Spanish, **Italiano**, Turkish, Slovak - Czech, Romanian, Portuguese, Polish, Dutch
6. Nota: Non ce bisogno di spedire il pacco, software inviato via mail, inviarci codice per fare attivazione licenza DPF e EGR

LISTA ECU SUPPORTATE:

FULL LIST PACK ECU v3.x (Last update: 2016)
DPF, EGR, Lambda, Hotstart, Flap, O2, DTC ECU List

DPF Removal Software v3.0.0 (DPF + Flap)

Alfa: EDC16C39 type1 and type2

Audi: EDC16UX, EDC16CP3 / 34, EDC16U31, EDC17CP14, Siemens PPD v1.1, V1.2, V1.3, EDC17CP44, EDC17C46, EDC17CP04, EDC16C34-4

BMW: EDC16C31 - 35, EDC16C31 (1MB), EDC17CP02, EDC16CP35, EDC16C31New, EDC16C35, EDC17CP45 EDC17C41

Chrysler: EDC16CP31

Chevrolet: EDC16C39

Citroen: EDC15C2, EDC16C34, EDC17C10, SID807

Fiat: EDC16C39 (Duchy), EDC16C39 JTD, MJD 6F3, 6F3 Doblo, EDC16C39 Generic, SID803A, Marelli 8F2, 8F3 Marelli,

Ford: EDC16C34, EDC16C34-2, EDC16C34-2.29, EDC16C34-5, SID 206, SID807, SID803MPC, SID803A, SID206 (SMAx type), SID206 Kuga, EDC16C34 Picasso Type, EDC16C3-9.18

Lancia: EDC16C39

Honda: EDC16C31, EDC17CP06, EDC16C31 (Advanced) Hyundai / KIA: EDC16C39-D373, Type2 EDC16C39 KIA, Hyundai EDC16C39 Caren, EDC16C39 SantaFe, EDC17C08

Iveco EDC16C39

Isuzu: Denso, Transtron DMax

Jaguar: SID204, EDC17CP11

Jeep: EDC16U1, EDC16CP31, EDC17C49

LandRover: EDC16C39-Ford, SID208

Mazda: Denso series at 3-8, EDC16C3, Denso Type CX7 with Adblue, EDC16C34

Mercedes: EDC16C31, Delphi DCM3.4, EDC16C31 Vito and Type2, EDC16CP36, EDC16C3,

EDC16C31 (2011+) EDC17CP10, M55 Error fixer
Mini Cooper: EDC16C35
Mitsubishi: Denso (Full 2 types supported), EDC16CP39
Nissan: Denso, EDC16C36, EDC16CP33 Type1 and Type2, SID305
Opel-Vauxhall: Denso, Denso Signum, EDC16C39, EDC16C9, EDC17C18 - C19, Marelli MJET 75-90cv, Z16DT Marelli Denso Signum, Z16DTC, Z19DT
Peugeot: EDC16C34, EDC15C2, SID803 MPC, Delphi DCM3.5, SID803A, Delphi DCM3.4
Porsche: EDC17CP44
Range Rover: EDC17CP11
Renault: EDC16C3 Type1 and Type2, EDC16C32, SID305, EDC16C11
Saab: EDC16C39, EDC16C9
Skoda: EDC17CP14, pCR2.1, Octavia19 Bosch, EDC17U01, EDC17CP20, EDC16CP44, EDC17U01
Seat: Siemens PPD V1.2, PCR 2.1 ,, EDC17U01, EDC17CP20, EDC16CP44
Subaru: Denso
Suzuki: EDC16C3 Type1 and Type2, EDC16C39
Toyota: EDC17CP07
Volvo: EDC16C31 Type1 and Type2, SID803MPC, EDC16C34, SID803A Type1 and Type2, EDC17CP22
VW: EDC16CP34, EDC16U31,, EDC17CP14, pCR2.1, EDC16CP34-4, EDC17U01, EDC17CP20, EDC16CP44 EDC17CP46, EDC17CP52, EDC17P24, EDC17CP44, EDC17CP54

All: EDC16 - EDC17 ECU's automatic DPF finder item switch

*: Some EDC16 and EDC17 ECU's solutions are all using internal switches.

Flap support list v3.0.0:

Audi a4, a6 EDC16CP34
Toureg EDC16CP34-4
Jeep EDC16CP31
Audi EDC16C34 Alternate
Audi V6TDI 3.0
Vectra C EDC
EDC15VM P0098 (EGR In Remover)
EDC16U1 Flap Solution
EDC17CP04
EDC17CP14

EGR Remover v3.0.0 (EGR + Hotstart + DTC)

Alfa: EDC16C39, EDC15C7, EDC16C8, EDC16C39 Generic
Audi: EDC16U1, EDC16U31 Type1 and Typ2, EDC15VM +, EDC17CP14, pCR2.1, EDC16CP34, EDC17C46
BMW: EDC16C31 Type1 and Type2, EDC16CP35, EDC16CP35, EDC17CP02
Chrysler: EDC16CP31
Citroen: EDC16C39, EDC16C34, SID803A, EDC15C3, SID803, EDC17C10, EDC16CP39
Dodge: EDC16U31-4 type1 and type2

Fiat: EDC15C7, EDC16C39 Type1 and Type2, EDC16C8, Marelli MJ 70-75-90CV, SID803A, Simos, Doblo Type
Ford: EDC16C3-9, EDC16C34, Visteon, EDC16C9 Cmax Type, SID206, SID804
Honda: EDC16C31
Hyundai: EDC15C7
Lancia: EDC15C7, EDC16C39, EDC16C8, Marelli MJ 70-75-90CV, SID803A
Land Rover: EDC16CP39, SID204
Iveco EDC16C39
Isuzu: Transtron (DMax Type)
Nissan: EDC16CP33, EDC16C3
Mazda: EDC16C34-2
Mercedes: EDC16C31 (types 1 and 2 mb), EDC15C6 (Switch and Remap), EDC16C31 Type2, EDC16CP31 M55 Fixer, EDC17CP10, EDC16CP36
Mini Cooper: EDC16C35
Mitsubishi: EDC16U31
Opel & Vauxhall: EDC16C3, EDC16C39, EDC16C36, Marelli MJ 70-75-90CV, Z19DTH, Denso, EDC17C18, EDC17C46, Delco
Peugeot: EDC16C34, EDC15C2, SID803A, EDC15C3, SID803, EDC16CP33, EDC16CP39
Range Rover: EDC17CP11
Renault: EDC16C3, EDC15C2, EDC16C3 Type2, EDC16CP36, Delphi DDCR
Saab: EDC16C9
Seat: EDC16U1, EDC17CP14, pCR2.1, PPD1.x
Skoda: EDC15VM +, EDC16U1, pCR2.1, PPD1.x, EDC17C46
Suzuki: Marelli MJ 70-75-90CV, EDC16C3
Volvo: EDC16, SID803, EDC17CP22
VW: EDC16U1, EDC17CP14, EDC17CP20, EDC16, pCR2.1, EDC16U34, EDC16CP34-4, PPD1.x, VW EDC17CP04
Hotstart
EDC16C31, EDC16U1, EDC15, Siemens PPDv1.1 - v1.2
Special EDC15C2 - C3 finder switch

Custom DTC Removers (Users can remove any code from DTC DTC Menu)

Fiat, Alfa, Chevrolet EDC15C7
PSA Group SID803a
Ford SID803
Ford SID803a
Ford SID206
PPDv1.x
Mercedes EDC16C31
VW EDC16U1 series

EDC17CP14 custom DTC Removing internal BETA (next update will be added)
Still in progress: Delphi DCM3.5, DCM3.7 EGR, Opel Denso, (in development, tested)


Automatic DTC Removers



Ford EDC16C34.2.30 total DTC
Alfa EDC16C39 total DTC
Audi EDC17C14 P2014 (Flap)
VM EDC15CVM P0098 (Flap)
Mercedes EDC16C31 DTC table full erase


Generic Solution Immo EDC17.

Software Display:

1. Professional DPF \ FAP - FLAP Remover 02.2016 FULL version!







PROFESSIONAL DPF REMOVER

Select Car - Model

- ☒ Alfa
- ☒ Audi
- ☒ BMW
- ☒ Chevrolet
- ☒ Chrysler
- ☒ Citroen
- ☒ EDC16 - EDC17 Generic Switch Search
- ☒ Fiat
- ☒ FLAP REMOVING
 - EDC16C34 CP34 Generic
 - EDC16U1 - P3101 P3102
 - EDC16U1- P3101 P3012 (Golf5)
 - EDC17CP04
 - EDC17CP14
 - Jeep EDC16CP31
 - MB EDC16C31 M55
 - Opel Vectra EDC16C9 (1MB)
 - Toureg EDC16C34
- ☒ Ford
- ☒ Honda
- ☒ Hyundai - KIA
- ☒ Isuzu
- ☒ Iveco
- ☒ Jaguar
- ☒ Jeep
- ☒ Lancia
- ☒ Land Rover
- ☒ Mazda
- ☒ Mercedes
- ☒ Mini Cooper (BMW)
- ☒ Mitsubishi

Log Window


Selected Model : EDC16CP34 Toureg Type
File Selected : C:\Users\Diag\Desktop\7L0907401.Bin
EDC16CP34 Toureg Type Detected OK.
Map or Switch Point1 has been disabled
Map or Switch Point2 has been disabled
Map or Switch Point3 has been disabled
Map or Switch Point4 has been disabled
Map or Switch Point5 has been disabled
Map or Switch Point6 has been disabled
Map or Switch Point7 has been disabled
Map or Switch Point8 has been disabled

Successfully Removed!!
PLEASE DONT FORGET FIXED THE CHECKSUM!

File Info

☐ Auto Savewww.ASCEquipments.com


Setup



2. Profesional EGR Remover 02.2016 FULL version!

On EGR Remover there are some special options on some cars like:

- * Fix Hotstart
- * IMMO
- * Special Custo DTC Solutions
- * Special EGR Solutions



PROFESSIONAL EGR REMOVER

Select Car - Model

- ⊕ Opel
- ⊕ Peugeot
- ⊕ Range Rover
- ⊕ Renault
- ⊕ Saab
- ⊕ Seat
- ⊕ Skoda
- ⊕ Suzuki
- ⊕ Volkswagen
 - EDC16CP34-4 Crafter Type
 - EDC16U1 - 1MB
 - EDC16U1 (Golf5 Type)
 - EDC16U34 (Caddy)
 - EDC16U34 Generic
 - EDC17C14 (2MB)
 - EDC17C46
 - EDC17CP04
 - EDC17CP20 (2MB)
 - Passat 1.9 TDI 105 (2MB)
 - PCR2.1 Generic
 - PCR2.1 Polo Type
 - PCR21 EGR+DPF New Models
 - PPD1.x
 - Touran EDC16U1 (1MB)
- ⊕ Volvo
- ⊕ HOTSTART
- ⊕ IMMO
- ⊕ Special Custom DTC Solutions
- ⊕ Special DTC Fast Solutions
- ⊕ Special EGR SOLUTIONS

Log Window

Selected Model : EDC16U1 - 1MB
File Selected : C:\Users\Diag\Desktop\7L0907401.Bin

EGR Map1 has been disabled
EGR Map2 has been disabled

Successfully Removed!!
PLEASE DONT FORGET FIXED THE CHECKSUM!

File Info

Filesize = 2097152
Checksum Value = A67Dh

